

CALTRANS QUALIFIED LABORATORY INSPECTION REPORT

Form TL-0113

Expiration date: March 04, 2016
 Inspected by: Afsaneh Ostovar
 IA No.: 096
 Phone: (916) 247-6311
 File: Materials Category 500

Laboratory: Clarkson Laboratory
 Address: 350 Trousdale Drive
 City: Chula Vista State: CA Zip: 91910
 Lab QC Mgr.: Laura E. Torres Email: laura@clarksonlab.com
 Telephone: (619) 425-1993 Fax: (619) 425-7917

A certified Independent Assurance (IA) visited this laboratory on (Date) March 04, 2015
 Only the equipment to be used on Caltrans construction projects and/or local construction projects on the National Highway System was checked for qualification.


At the time of Caltrans Qualification, this laboratory had all necessary equipment to perform the tests methods indicated below. Testing personnel shall be Caltrans Qualified and possess a current Caltrans Certificate of Proficiency Form TL-0111 prior to performing any sampling or testing.

<u>CT 417</u>	<u>CT 422</u>	<u>CT 643</u>				
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____

A visual check was performed and documents provided as necessary for the following items:

- Facility Safety Manual
- Laboratory Procedures Manual
- Laboratory Quality Control Manual
- Proper test equipment
- Copies of current applicable test procedures
- Calibration and service documentation
- Calibration stickers affixed to test equipment (dated within the 12 months)

On March 04, 2015 this laboratory was Caltrans Qualified by AFSANEH OSTOVAR
Date *Printed name of IA person*


Signature of IA person

BT